## FIELD INSPECTION REPORT

24.

Date of Inspection :		Dist	District:	
Division :		Len	Length (km): 0.500	
		VH-80 Ramana	bandit to Kishor	yadar V
Schem	e/Programme:	MAINTBNANCE	The state of the s	AND DESCRIPTION OF THE PERSON
Packa	ge No.:		d ld No 20803701	2840
Status	of the Project:	Ongoing/Completed/Unde	r Maintenance	
Work	is a case of:	New Connectivity/Up grac		Remails
Sl. No		Parameters in he che	elked	10.10
1.	Pavement		And the second	
a)	Road Junction condition			S/U_
b)	Condition of Surfacing			S/U
	The state of the s			S/U
c)	Riding Quality			S/U
d)	Road Camber			77. 01
e)	Whether free from defects such as visible cracks, exposed Yes/No aggregates in case of CC Pavement.			Yes/No .
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
	Compaction of flank/slope & raincuts if any			Yes/No
g)	Source Provide the Source Transport	and the second s		
2,,,	Cross Drainage			S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing Wans, Slab III Rec curvets			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance His	tiony		(4.143. A)
a)	Status of ATR's			, ,
-y (	the page of the second	The second secon	SENDENTE MEDICAL CONTROL OF STREET, AND ST	9

Overall Rating

	THE RESERVE OF THE PROPERTY OF
Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	Y

12-7-

(Signature)

NAME: