

Inspection of Roads Under MR (3054) in CHAUSA block

FIELD INSPECTION REPORT

Date of Inspection : 08.12.2020		District: Puzos	
Division : Puzos		Length (km): 1.500	
Name of the Road: Puzos - Chausa Bazar more to Ghoshpur, Kalaxai Maidantoli Under MR (3054)			
Scheme/Programme: MAINTENANCE			
Package No.: 2217-18		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N.A.
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NB.	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

m. Jyoti
10/12/2020
N.E.

(Signature) 08.12.2020

NAME: Maje Nand Boud

DESIGNATION: I.E