

FIELD INSPECTION REPORT

Date of Inspection : 04.12.2020	District: Munger
Division : Munger	Length (km): 0.875 / 1000
Name of the Road: Sitakund Mainroad & Mai Village Via Shiv Gram Dham	
Scheme/Programme: MAINTENANCE	MR - old
Package No.:	Road Id No.: 20803708153 / 2080370841
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	Entry position, Main sign board, Maintenance board NH 301 & 302

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Ravi Shankar Mondal
J.E.

Mandal
04.12.2020
J.E.
(Signature)

NAME:

DESIGNATION: