## FIELD INSPECTION REPORT

Date of Inspection : \	12/20	District: Robtal
Division: Sasaram-2		Length (km): 1.930 K.M
Name of the Road: No	Soigen Mais	Rood - Barauni
Scheme/Programme:	AS TIGEN Main Rood - Barauni MAINTENANCE	
Package No.:	and the second s	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of tlank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	THE TANK TO A
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Unsatisfactory (U)
Note - Tendels Stafe

Diwesh Pd. Sixh

(Signature)