FIELD INSPECTION REPORT

Date of Inspection: 3	112/20	District: PATHA
Division: Dare 1947		Length (km):
Name of the Road: Set	ter Panchmuhani	to Balua pathonya Load
Scheme/Programme:	MAINTENANCE	
Package No.: MK/H] 17	- 20 Danopur 09	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
W	New Connectivity/I In gradation/ Maintenance	

Work	s a case of:	THE WALLEY THE
Sl. No.	Param ters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
	Riding Quality	S/U
c)		S/U
e)	Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	g S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3,-	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200n stones/Pavement road markings are provided and maintained	Yes/No
4,6	Gompliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	The second second

Work not started

\$102/12/200

3/12/220 3/12/220 4/E. Maraer

(Signature)

NAME: Subish chan to his

DESIGNATION:

DE