

Fatulya

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Patna</u>
Division : <u>Patna</u>	Length (km): <u>0-012</u>
Name of the Road: <u>Fatehpur Vekh Strige Pul to Samip Hising H.P. Culvert</u>	
Scheme/Programme: MAINTENANCE	<u>Banane diw Pul ke niche tane mitti ki sagayi</u>
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

No provision of Maintenance work.

Satisfactory (S)	<u>N/A</u>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Tai Prakash Singh.

DESIGNATION:

J.E.

03/12/2020
(Signature)