

FIELD INSPECTION REPORT

Date of Inspection :- 11/12/2020	District :- Buxar	Buxar
Division :- Buxar	Length (km):	
Name of the Road :- Dudharchak Shivala to Majharia Bandh.		
Scheme/Programme:	MAINTENANCE	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U/N.A
b)	Condition of Surfacing	S/U/N.A
c)	Riding Quality	S/U/N.A
d)	Road Camber	S/U/N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No/N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U/N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U/N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U/N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History <i>There is no provision of five year maintenance. Road is damaged</i>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)✓	
Unsatisfactory (U)	

NAME:

REDMI NOTE 6 PRO
MI DUAL CAMERA

(Signature)

[Signature]
11.12.20