

FIELD INSPECTION REPORT

Date of Inspection :- 11/12/2020	District :- Buxar
Division :- Buxar	Length (km):
Name of the Road :- Chhotki Basauli more in Buxar Nuharnad to Barki Basauli.	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U/N.A.
b)	Condition of Surfacing	S/U/N.A.
c)	Riding Quality	S/U/N.A.
d)	Road Camber	S/U/N.A.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No/N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U/N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U/N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U/N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	Compliance History:- There is no provision for five year maintenance. Road is damaged.	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)✓	
Unsatisfactory (U)	



REDMI NOTE 6 PRO
MI DUAL CAMERA

(Signature) 11.12.20