

FIELD INSPECTION REPORT

Date of Inspection : 10.12.20		District: Buxar
Division : Buxar		Length (km): 22 km
Name of the Road: Daiterhabe se Kankhot AJMDR tk		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: old MR
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		Pitt year maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	Maintenance is in progress ✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Maintenance proposed Yes/No
f)	Contraction Joints provided or not (CC Pavement)	(N/A) Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (N/A)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	(N/A) S/SRI/U
c)	Condition of railings/slab/approach for Bridges	(N/A) S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

N.K. Himanshu

DESIGNATION:

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, राजपुर

(Signature)

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, राजपुर

Scanned with CamScanner

Scanned with CamScanner