	Inspection: (	13/12/2020	- District: Lama	,	
Division			Length (km): 4.950 ·		
	the Road: N	H-30A Jan	ardanfur to Barina-Ba	lwa Path	
	Programme:	MAINTENANC			
Package		old.	Road Id No.:		
	f the Project:		eted/Under Maintenance		
Line Laboratoria	a case of:	New Connectivi	ty/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S/U_	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No M	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No M	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U ∧	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U N	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance H	istory			
a)	Status of ATR's & any others			No	
Overall R	Pating .			11 ))	
Overall	taing •	Satisfactory (S)		5	
		C-4:-C41	A T A (CDT)		

Satisfactory (S)	// <u>/</u> // //
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Jai Drakash Lengh, TION: J.E

**DESIGNATION:**