

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020
 Division: Patna
 Name of the Road: Patna Bypass Road to Ghazipur
 Scheme/Programme: MAINTENANCE
 Package No: PK-1/2019-20/10/20
 Road Id No:
 Status of the Project: Ongoing/Completed/Under Maintenance (New Maintenance)
 Work is a case of: New Connectivity for promotion Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement — N/A	SU
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank slope & raincuts if any	Yes/No
2.	Cross Drainage — N/A	
a)	Condition of head walls in Home pipe culverts including its painting	SSRIU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SSRIU
c)	Condition of railings/slab approach for Bridges	SSRIU
3.	Road Furniture — N/A	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History — NO	
a)	Status of ATR's & any others	

Overall Rating :

Work is yet to start.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Pratish Chandra Prashad

DESIGNATION:

A.E.

(Signature) 02/12/2020