

FIELD INSPECTION REPORT

Location : District : Bhagalpur		
Location : Bhagalpur Length (Km) :		
Name of the Road : <u>Nathnagar to Radhanagar (Part-A)</u>		
Scheme / Programme : MAINTENANCE		
Package No. : Road Id No. :		
Status of the Project: Ongoing / Completed / Under Maintenance		
Work is a case of : New Connectivity / Up gradation / Maintenance <u>Double entry</u>		
SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S / U
b)	Condition of Surfacing	S / U
c)	Riding Quality	S / U
d)	Road Camber	S / U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No
f)	Contraction Joints provided or not (CC Pavement)	Yes / No
g)	Compaction of flank/slope & raincuts if any	Yes / No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	NO
Overall Rating : <u>Double entry</u>		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

NAME :

Lakshman p.d. Yadav

DESIGNATION :

J.C.

(Signature)

Lakshman
07/12/2020
J.C.