## FIELD INSPECTION REPORT

Date of	Inspection: 3 12 20 W District: 00=14	
Division	1: Demohur	
Name o		
Scheme	Programme: MADITENANCE	19 Icela.
Packag	e No.: m1/H/15- 20 Deputy of D	
Status o	of the Project: Ongoing/Completed/Under Maintenance	
Work is	Sa case of: New Connectivity/Up gradation/ Maintenance	•
Sl. No.	Parameters to be checked	Remarks
i li	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	. S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4,	Compliance History	
a)	Status of ATR's & any others	
Carry Constitution of the	3000 200 State Control of the Contro	

Overall Rating

Satisfactory (S)	143
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	(K

work not start - of

303127000

3112/2020 A.E. Maner

(Signature)

NAME:

Susech ehrer hys

DESIGNATION: