FIELD INSPECTION REPORT

	TIEDO MISTAGRANIA	1
	Inspection: 3/12/20 District: PATNA	\$
Division: DANAPUR Length (km): 2.4		
Name of the Road: Pon usy Rd to fall keth		
	e/Programme: MAINTENANCE	
Packag		
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance		
Maria China		
SI No.	Parameters to be checked	Remarks
	Payement at the second	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2, ,	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3,	Road Furniture	
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
	Compleme History 12 (1947)	
a)	Status of ATR's & any others	
	10.1. 10.1 (1)	

Overall Rating

work not started

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

3)12tro J.E Bolita (Anil Kumar)

NAME:

DESIGNATION:

(Signature)