

# FIELD INSPECTION REPORT

| Date of Inspection:                         | 12-12-2020                                                                                                               | District:   | Darbhanga |
|---------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|-------------|-----------|
| Division:                                   | Darbhanga-2                                                                                                              | Length(Km): | 3.443     |
| Name of Road:                               | ToG to Kanokhar                                                                                                          |             |           |
| Scheme/Programme:                           | Maintenance PMGSY/Routine Maintenance                                                                                    |             |           |
| Package No.                                 | BR-10R-219                                                                                                               | Road Id No. |           |
| Status of the Project:                      | Ongoing/Completed/ Under Maintenance                                                                                     |             |           |
| Work is a case of :                         | New Connectivity/Up gradation/ Maintenance                                                                               |             |           |
| S No.                                       | Parameters to be Checked                                                                                                 | Remarks     |           |
| <b>1</b>                                    | <b>Pavement</b>                                                                                                          |             |           |
| a)                                          | Road Junction condition                                                                                                  | S/✓         |           |
| b)                                          | Condition of Surfacing                                                                                                   | S/✓         |           |
| c)                                          | Riding Quality                                                                                                           | S/✓         |           |
| d)                                          | Road Camber                                                                                                              | S/✓         |           |
| e)                                          | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement                              | Yes/No      |           |
| f)                                          | Contraction Joints provided or not (CC Pavement)                                                                         | Yes/No      |           |
| g)                                          | Compaction of flank /slope & raincuts if any                                                                             | Yes/No      |           |
| <b>2</b>                                    | <b>Cross Drainage</b>                                                                                                    |             |           |
| a)                                          | Condition of head walls in Hume pipe culverts including its painting                                                     | S/SRI/✓     |           |
| b)                                          | Condition of Abutment & Wing walls , Slabs in RCC culverts                                                               | S/SRI/✓     |           |
| c)                                          | Condition of railing /slabs/ approach for Bridges                                                                        | S/SRI/✓     |           |
| <b>3</b>                                    | <b>Road Furniture</b>                                                                                                    |             |           |
| a)                                          | Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained | Yes/No      |           |
| <b>3</b>                                    | <b>Compliance History</b>                                                                                                |             |           |
| a)                                          | Status of ATR's & any others                                                                                             | NO          |           |
| Overall Rating: SRI                         |                                                                                                                          |             |           |
| Satisfactory (S)                            |                                                                                                                          |             |           |
| Satisfactory but requires Improvement (SRI) |                                                                                                                          | SRI         |           |
| Unsatisfactory (U)                          |                                                                                                                          |             |           |

Note - due to partial submergence and flow of water during flood period a very short length has very few pots.

Name: ANIL KUMAR

Designation: EXECUTIVE ENGINEER

(Signature)

EXECUTIVE ENGINEER  
DARBHANGA-2