

FIELD INSPECTION REPORT (Routine Maintenance)

Date of Inspection:	12-12-2020	District:	Darbhanga
Division:	Darbhanga-2	Length(Km):	1.590 km
Name of Road:	To: Narayanpur to Kaurth Kawai [BR-10R-207]		
Scheme/Programme:	Maintenance PMGSY/Routine Maintenance		
Package No.	BR-10R-207	Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/✓
b)	Condition of Surfacing	S/✓
c)	Riding Quality	S/✓
d)	Road Camber	S/✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank /slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/✓
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/✓
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/✓
3	Road Furniture	
a)	Whether sign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No
3	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating: **SRI**

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Note - due to Submergence and flow of water during flood period a very short length has some pots.

Name: **ANIL KUMAR**

Designation: **EXECUTIVE ENGINEER**


12-12-2020
(Signature)
EXECUTIVE ENGINEER
DARBHANGA -2