

FIELD INSPECTION REPORT

Date of Inspection : 12.12.2020		District: Darbhanga.
Division : RWD WDiv Darbhanga-2		Length (km): 0.950 KM
Name of the Road: PWD Road to Ghop Tola.		
Scheme/Programme: MAINTENANCE		MMGSY
Package No.:	Road Id No.:	
Status of the Project: Ongoing /Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: Kumar Chandraj.

DESIGNATION: Asst. Engineer.

कुमार चन्द्रम
12.12.2020

(सहायक अभियन्ता
ग्रामीण कार्य विभाग
कार्य अवर प्रभु)

* वर्ष 2020 में आभी भयंकर बाढ़ के कारण पथ में कई जगह Raincuts हो गया है एवं पथ के नदी किनारे अवस्थित होने के कारण पथ टूट गया था जिसमें यातायात बहाल करने हेतु Temporary Restriction का कार्य किया गया है।