

FIELD INSPECTION REPORT

Date of Inspection :	11.12.2020	District:	Gaye
Division :	RWD Imangang	Length (km):	4.375 km
Name of the Road:	L634-L635 to Beahmorea		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR/2 R 889	Road Id No.:	-
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U - S	
b)	Condition of Surfacing	S/U - S	
c)	Riding Quality	S/U - S	
d)	Road Camber	S/U - N/A	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - yes	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - yes	
g)	Compaction of flank/slope & raincuts if any	Yes/No - Raincuts found in	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N/A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m Stones Pavement road markings are provided and maintained	Yes/No - turning board not found.	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	- SRI -
Unsatisfactory (U)	

11.12.20.
(Signature)

NAME:

Anil Kr Singh
AE RWD Imangang.