

FIELD INSPECTION REPORT

Date of Inspection :	11.12.20	District:	Gaya
Division :	Gaya	Length (km):	3.052KM.
Name of the Road:	LOBB-Pananiga to Koodwariga		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-12R 890	Road Id No.:	—
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance —		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U — S
b)	Condition of Surfacing	S/U — S
c)	Riding Quality	S/U — S
d)	Road Camber	S/U — N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U — N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Nilay

(Signature)

NAME:

Nilay kumar Singh
AE RWD Indraganj.