

FIELD INSPECTION REPORT

Date of Inspection : 11.12.2020	District: Gaya
Division : RWD Imangany	Length (km): 0.791
Name of the Road: L062 - Majuri khurd to Pachim tala	
Scheme/Programme: MAINTENANCE	
Package No.: BR-12R 873	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - S
b)	Condition of Surfacing	S/U - U
c)	Riding Quality	S/U - S
d)	Road Camber	S/U - N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No - rain cuts & shrubs found
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U - N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	(U)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Niraj Kr Singh)
(Signature)

NAME:

Niraj Kr Singh
AE RWD Imangany (Banke Bazar)