

FIELD INSPECTION REPORT

Date of Inspection : 11.12.2020	District: Gaya
Division : RWD Imangang	Length (km):
Name of the Road: Dabi As Than Tola to LD25	
Scheme/Programme: MAINTENANCE	GTSNY
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/L — S
b)	Condition of Surfacing	S/L — S
c)	Riding Quality	S/U — S
d)	Road Cumber	ST — N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No —
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No — rain cuts found.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/ — N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/ — N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(SRI)
Unsatisfactory (U)	

NAME:

Wing ker Singh
AE RWD Imangang

(Signature)