

FIELD INSPECTION REPORT

Date of Inspection :	11.12.20	District:	Gaya
Division :	RWD Imongang	Length (km):	0.830
Name of the Road:	Kasigadih to SH 69		
Scheme/Programme:	MAINTENANCE		GTSNY
Package No.:	—	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U — S
b)	Condition of Surfacing	S/U — S
c)	Riding Quality	S/U — S
d)	Road Camber	S/U — N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <i>cracks found in cc Pav.</i>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No <i>raincut & shrubs found.</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U — N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U — N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	(U)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
(Signature)

NAME:

Niraj Ver Singh
AE RWD Imongang.