

FIELD INSPECTION REPORT

Date of Inspection : 13.12.2020	District: Dushkunge
Division : Road No. 2	Length (km): 1.050 km
Name of the Road: Jagat Phikar Path to Jagat Chauri	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New / Connectivity / Up gradation / Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/N/A
b)	Condition of Surfacing	✓/N/A
c)	Riding Quality	✓/N/A
d)	Road Camber	✓/N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/S/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	—

NAME: KUMAR Chandan

DESIGNATION: Asst Engineer

कमल चन्दन
13.12.2020
(Signature)

सहायक अभियन्ता
ग्रामीण कार्य विभाग
कार्य अवर प्रमुख, सिविल

* वर्ष 2020 में भारी वर्षा के कारण पथ के Surface Damage हो गया है। आगामी ही सुधार हेतु Temporary Restoration कार्य किया जा रहा है।