

FIELD INSPECTION REPORT

Date of Inspection : 12.12.2020	District: Daxbhanga.
Division : RWDW (b) Daxbhanga-2	Length (km): 0.560 KM.
Name of the Road: To2 To Sonawan	
Scheme/Programme: MAINTENANCE PROJECT	
Package No.: ———	Road Id No.: ———
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/L
b)	Condition of Surfacing	✓S/L
c)	Riding Quality	✓S/L
d)	Road Camber	✓S/L
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—SRI
Unsatisfactory (U)	—

NAME: KUMAR Chandan
DESIGNATION: Asst Engineer

कुमार चन्दन
12-12-2020
(Signature)
सहायक अभियन्ता
प्राथमिक कार्य विभाग
कार्य प्रवर्धन विभाग

* वर्ष 2020 में भारती ब्रैकट नाट से पत्र के पूरी तरह submerged हो जाने के कारण पत्र में damage हो पावेल्टी हो गया था। Temporary स्थापना से कार्य भरोसा प्रदान हो रहा है।