

# FIELD INSPECTION REPORT

Date of Inspection : 11.12.2020		District: Darbhanga.
Division : RWD W(Div) Darbhanga-2		Length (km): 0.487 KM.
Name of the Road: MIRJAPUR JANAI RANCHELA PATH TONARKATIYA.		
Scheme/Programme: MAINTENANCE		GTSNY.
Package No.:		Road Id No.:
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/A
b)	Condition of Surfacing	✓S/A
c)	Riding Quality	✓S/A
d)	Road Camber	✓S/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: Kumar Chandig.  
DESIGNATION: Jstt. Engineer.

कुमार चन्दग  
(Signature) 11.12.2020  
JE ग्रामीण कार्य विभाग  
कार्य अवर प्रमंडल, सिंहवाड़ा