

FIELD INSPECTION REPORT

Date of Inspection :	12/12/2020	District:	Jamui
Division :	Jamui	Length (km):	1.002 km
Name of the Road:	H36 - TDI to Musahazi		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	20804100227
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SAT S
b)	Condition of Surfacing	SAT S
c)	Riding Quality	SAT
d)	Road Camber	SAT
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/ No
f)	Contraction Joints provided or not (CC Pavement)	Yes/ No
g)	Compaction of flank/slope & raincuts if any	Yes /No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/ SRI/U
c)	Condition of railings/slab/approach for Bridges	S/ SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes /No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:

 12/12/20
 12/12/20
 AE, Laxmipur

(Signature)