

FIELD INSPECTION REPORT

Date of Inspection : 12-12-2020		District : GAYA
Division : Neemchak Bathani ; Sub Division - Manpur		Length (Km.) : 2.111 Km.
Scheme/Programme: NABARD	MAINTENANCE	Gaya - Nawada Road NH-82 to Masautha Khurd.
Package No. : N/A		Road Id No. : N/A
Status of the Project : Under Maintenance		Ongoing/Completed/Under Maintenance
Work is a case of : Maintenance		New Connectivity/Up gradation/Maintenance
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as <u>visible cracks</u> , exposed aggregates in case of CC Pavement.	NO. Yes/No
f)	Contraction Joints provided or not (CC Pavement)	YES Yes/No
g)	Compaction of flank/slope & raincuts if any	NO. Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES. Yes/No
4	Compliance History	
a)	Status of ATR's & any others. No ATR. Both Side Flank requires improvement.	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 12/12/2020.
 A.E.R.H.D.
 Manpur.