

FIELD INSPECTION REPORT

Date of Inspection : 12.12.2020		District: N. Champaran	
Division : Bettiah		Length (km):	
Name of the Road: C-021 (from bridge) Dul to Idgah Jolga			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.: 971NY		Status of the Project: Ongoing/Completed/Under Maintenance <u>Completed</u>	
Work is a case of:		New Connectivity/Up gradation/ Maintenance <u>New Connectivity</u>	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S ✓ S/U	
b)	Condition of Surfacing	S ✓ S/U	
c)	Riding Quality	S ✓ S/U	
d)	Road Camber	S ✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes ✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	N/A ✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes ✓ Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A ✓ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	N/A ✓ S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes ✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO ✓	

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
12/12/2020
(Signature)

NAME: SUNIL KUNAR

DESIGNATION: J.E