

FIELD INSPECTION REPORT

Date of Inspection :	11/12/2020	District:	Gurgaon
Division :	RWD Imanganj	Length (km):	0.850
Name of the Road:	Bankebazar Prakhand ke baatal Panchayat ke gram baatal se mulchya path		
Scheme/Programme:	MAINTENANCE		MNP
Package No.:	—	Road Id No.:	—
Status of the Project:	Ongoing/Completed/Under Maintenance		Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Routine maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U - S
b)	Condition of Surfacing	S/U - S
c)	Riding Quality	S/U - S
d)	Road Camber	S/U - N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

— SRI —

11.12.20.

(Signature)

NAME:

Nsing Len Singh
Asst. Engg RWD
Imanganj.