

FIELD INSPECTION REPORT

Date of Inspection: 11.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 2.00 Km
Name of Road : Lagama to Babakewal sthan.		
Scheme / Programme: MAINTENANCE		MR New 2018
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance <i>ongoing</i>		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance <i>up gradation</i>
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	—
b)	Condition of Surfacing	—
c)	Riding Quality	—
d)	Road Camber	—
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	—
f)	Constraction Joint provided or not(CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridge	—
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>Mark been fixed</i>
4	Compliance History	
a)	Status of ATR's & any others	—

Stipulated date of compliance is 10.9.2020. Till now BT work not started

Overall Rating :

Satisfactory(S)	—
Satisfactory but requires Improvement(SRI)	<i>SRI</i>
Unsatisfactory(U)	—

[Signature]
11.12.2020
(Signature)

NAME: *Anil Prasad*
DESIGNATION: *JE*