


FIELD INSPECTION REPORT

Date of Inspection: 13/12/16		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 4.520km
Name of Road: पटना रोड से NH 103 तक 1		
Scheme / Programme: MAINTENANCE		
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	11
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	-
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridge	-
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	-
4	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	SRI


(Signature)

NAME: Dhanaojay Prasad
DESIGNATION: J.E.