

FIELD INSPECTION REPORT

Date of Inspection: 13/12/16	District: Samastipur
Division: RWD Dalsinghsarai	Length(km): 2.210 km
Name of Road : मन्सीचा चौक से रोजीत राय मुरिगा के बाट तक	
Scheme / Programme: MAINTENANCE	
Package No: मन्सीचा चौक से	Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/ Up gradation/ Maintenance	

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	N/A
b)	Condition of Surfacing	..
c)	Riding Quality	..
d)	Road Camber	..
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	..
f)	Constraction Joint provided or not(CC Pavement)	..
g)	Compaction of flank/slope & raincuts if any	..
2	Cross Drainage	..
a)	Condition of head walls in Hume pipe culverts including its painting	..
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	..
c)	Condition of railings/slab/approach for Bridge	..
3	Road Furniture	..
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	..
4	Compliance History	
a)	Status of ATR's & any others	..

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

[Signature]

(Signature)

NAME:

DESIGNATION: J. E.