

FIELD INSPECTION REPORT

Date of Inspection: 12.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.200 Km
Name of Road : To 2 to muslim gola.		
Scheme / Programme: MAINTENANCE		new MP 2018
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance <i>ongoing</i>		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance <i>- up gradation</i>
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓
f)	Constraction Joint provided or not(CC Pavement)	✓
g)	Compaction of flank/slope & raincuts if any	✓
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	✓
c)	Condition of railings/slab/approach for Bridge	✓
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓
4	Compliance History	
a)	Status of ATR's & any others	NO

Stipulated date of Completion is 16.9.2020 but till now RT/Surface work not started.

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

[Signature]
12/12/2020
(Signature)

NAME: *Anil Prasad*
DESIGNATION : *DS*