## FIELD INSPECTION REPORT

Date of Inspection :-		District: Khagaria			
Division: Shagazea.		Length (Km):-			
Name of I	Road: Rabbo Ke gamno 30 Rankovich me Bans	argat Fonte funchagat me mayers inden our Agen asker panchagat to mult	y North		
Scheme/Programme :-		Mainténance			
Package No. :-		Road ID No. :-			
Status of Project :-		Ongoing/Complete/Under Maintenance			
Work is a	case of :-	New Connectivity/Up gradation/ Maint	enance		
Sl. No.	Parameters	to be cheeked	Remarks		
1.	Pavement				
a)	Road Junction Condition		S/U		
b)	Condition of Surface		S/U		
c)	Riding Quality		S/U		
d)	Road Camber		S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No		
Ŋ	Contruction Joints provided or not (CC Pavement)		Yes/No		
g) -	Compaction of flank/slope & raincuts if any		Yes/No		
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		S/SRI/U		
c)	Condition of railings/slab/approach for Bridges		S/SRI/U		
3.	Road Furniture				
a)	Whether sign boards/informatory/ Pavement road markings are provide	Yes/No			
4.	Compliance History				
a)	Status of ATR's & any others				

-		-				
O	vera	m	Ra	tir	10	٠

Satisfactory (S)	M9.
Satisfactory but requires Inprovement (SRI)	
Unsatisfactory (U)	

Note: - Out of maintenance.

(Signature) 1220