

FIELD INSPECTION REPORT

Date of Inspection :-		District :- <i>Khagaria</i>
Division :- <i>Khagaria</i>		Length (Km) :-
Name of Road :- <i>Khagaria jilla Aantagar Hatipur Pandhaya me Nista Mahan</i> <i>Ashon de frongi Ashon hote huye Baidya mukharita Sadak</i>		
Scheme/Programme :-		Maintenance
Package No. :-		Road ID No. :-
Status of Project :-		Ongoing/Complete/Under Maintenance
Work is a case of :-		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction Condition	S/U
b) -	Condition of Surface	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Constrution Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a) -	Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	<i>NA</i>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

note: Out of Maintenance

(Signature)

11/12/2020
Agarwal