

FIELD INSPECTION REPORT

Date of Inspection :-	District :-	Khagaria
Division :-	Length (Km) :-	2.20 km
Name of Road :-	Budhwa se haripur PMGSY path	
Scheme/Program :-	OLD M/R	Maintenance
Package No.	Road ID No. :-	
Status of Project :-	Ongoing/Complete/Under Maintenance ✓	
Work is a case of :-	New connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Condition	S/U
b)	Surface	S/U ✓
c)	Quality	S/U
d)	Colour	S/U
e)	Free from defects such as visible cracks, exposed aggregates in pavement.	Yes/No
f)	Joints provided or not (CC Pavement)	Yes/No
g)	Flank/slope & raincuts if any	Yes/No
2.	Drainage	
a)	Head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Abutment & Wing walls, Slab, RCC Culverts	S/SRI/U
c)	Trailings/slab/approach for Bridge	S/SRI/U
3.	Structure	
a)	Sign boards/information/caution board, km & 200 m stone/road markings are provided and maintained	Yes/No
4.	History	
a)	IR's & any others	

Overall

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

10/12/20
J.E