


FIELD INSPECTION REPORT

Date of Inspection :- 05/12/2020		District :- Khagaria.	
Division :- Khagaria.		Length (Km) :-	
Name of Road :- Khagaria Gosala To Maraz Path.			
Scheme/Programme :- Old MRR		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :- Under Maintenance		Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction Condition		✓S/U
b)	Condition of Surface		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ✓
f)	Constrution Joints provided or not (CC Pavement)		NA Yes/No
g)	Compaction of flank/slope & raincuts if any		NA Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		NA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges		NA S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained		✓Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)


 05/12/2020
 J.B.
 Khagaria.