


FIELD INSPECTION REPORT

Date of Inspection :	11-12-20	District:	Machhapur
Division :	Uda Kishanpur	Length (km):	1.43
Name of the Road:	Const. of Rd From RWD Rd to Rajgarh Purua Sima.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	21004801017.
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. only B.T. surface	Yes/No
f)	Contraction Joints provided or not (CC Pavement) only B.T. surface	Yes/No
g)	Compaction of flank/slope & ruincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U


 12/12/20
 (Signature) J. E. Bhatnagar

NAME: