FIELD INSPECTION REPORT

		FIELD INSPE	CHOREC	-		
Date of Inspection: 2 12 2020			District:	_	patma	
Division: Pali fami			Length (km):	0.83	. 830 K-M-	
		pair of road	brom Khajyri	to Pani	LATH VIQUE GELL	
	/Programme:	MAINTENANCE	111111			
Packag			Road Id No.:			
Status of the Project:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance				
Work is a case of:		Parameters to be checked		Remarks		
Sl. No.		Parameters to			1.5	
1.	Pavement	Pavement NIA				
n)	Road Junction condition				S/U S/U	
b)	Condition of Surfacing					
c)	Riding Quality				S/U	
	Road Camber				S/U	
d) e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No	
	Contention le	Contraction Joints provided or not (CC Pavement)				
1)		1			Yes/No	
g)	Compaction o	ompaction of flank/slope & raincuts if any				
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U	
c)	Condition of railings/slab/approach for Bridges				S/SRI/U	
3.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					
4.	Compliance History				一个一个	
a)	Status of ATR's & any others					
	Note . Th.	e road has	heen trans	iberol.	to R.e.D	
verall Rating :		Satisfactory (S)			Satiskact	
		Satisfactory but requires Improvement (\$RI)				
		Unsatisfactory		,	10	
		21131111111111	(-/			

12.12 2020 NAME: J. F. 85 Rom-12/12/2020 A.E.

(Signature)