

FIELD INSPECTION REPORT

Date of Inspection:	02/12/XX	District:	Motihari
Division:	Pakan Doyal	Length(Km):	0.55
Name of Road:	Pakan Doyal Kothibazar to Patali		
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank /slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No
3	Compliance History	
a)	Status of ATR's & any others	

Overall Rating:

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Presently this road is under SRI maintenance viz. Chorma Kothibazar Chowk to Patali, Inspection of which has already been done on dated - 03/12/XX and graded "U"

Name: K Sinha
 Designation: 12/12/XX
02/12/XX