

FIELD INSPECTION REPORT

FIELD INSPECTION REPORT		
Date of Inspection:	12/12/xx	District: medinipur
Division:	Pakari Dayal	Length(Km): 9.0
Name of Road:	Dhaka to Pakari Dayal	
Scheme/Programme:	Maintenance ✓	
Package No.		Road Id No.
Status of the Project:	Ongoing/Completed/ Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Ruling Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank /slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
	Road Furniture	
a)	Whether sign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No
	Compliance History	
a)	Status of ATR's & any others	
Rating:		
Satisfactory (S)		
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

↳ Note! - Presently this road is under sys maintain viz. Balkan Dayal to Dhaka - P-2, inspection of which has already been done on dated 03/12/xx and graded "U".

Kishka
12/27/2011
JE/POI.