

①

FIELD INSPECTION REPORT

Date of Inspection: 12-12-2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 0.900 km	
Name of Road : Balance part of Road from Bhagwanpur Kamla NH28 Hari Bansh Narayan			
Scheme / Programme: MAINTENANCE		old maintain. Singh ghat Kamla East mandu	
Package No:		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance - out of maintain			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance -	
Sl. No	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction Condition	There was no provision	
b)	Condition of Surfacing	for 5 year Maint.	
c)	Riding Quality		
d)	Road Camber	The road is taken	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	under	PM GY - III
f)	Constraction Joint provided or not(CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridge		
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	—
Unsatisfactory(U)	—

[Signature]
12/12/2020
(Signature)

NAME:

Anil Prasad

DESIGNATION:

JE