

FIELD INSPECTION REPORT

Date of Inspection: 12-12-2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 1.500 km	
Name of Road: NH 28 Harbanshi Maryam Singh gar to Kamala East Mandir		
Scheme / Programme: MAINTENANCE	MR Old.	
Package No:	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance Beyond Maint.		
Work is a case of:	New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	There was no provision for 5 years Maint.
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	The road is taken
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	under PMGSY-17
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	-
Unsatisfactory(U)	-

12/12/20
(Signature)

NAME: Anil Prasad
DESIGNATION: JE