

# FIELD INSPECTION REPORT

Date of Inspection: 12/12/2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 3.600 km	
Name of Road : Chaitaulat to Akha Pans Village Pans.			
Scheme / Programme: MAINTENANCE		MR old -	
Package No:		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance Beyond Maint			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked	Remarks	
1	<b>Pavement</b>		
a)	Road Junction Condition	Road proposed for Candidate's date road in PMGSY-II.	
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	There was no provision for 3 <sup>rd</sup> year Maint.	
f)	Constraction Joint provided or not(CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls , Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridge		
3	<b>Road Furniture</b>		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4	<b>Compliance History</b>		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	5
Satisfactory but requires Improvement(SRI)	—
Unsatisfactory(U)	—

  
 12/12/2020  
 (Signature)

NAME:

DESIGNATION:

Anil Prasad

SB