


# FIELD INSPECTION REPORT

Date of Inspection: 11.12.2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 2.5012	
Name of Road : maheshpatti Babulal chowle to Dhamua paeel under Usz yarpur Maek.			
Scheme / Programme: MAINTENANCE - MR old.			
Package No:		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	

Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	There was no provision of 5 year Maint. DRP for New Maint Policy of the road has been sent to Department. The road is also taken under PMGSY III
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	5
Satisfactory but requires Improvement(SRI)	1
Unsatisfactory(U)	0

  
 11.12.2020  
 (Sign e)

NAME:

DESIGNATION :

Anil Prasad

JE