


# FIELD INSPECTION REPORT

Date of Inspection: 12-12-2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 1.750 km	
Name of Road: NH 28 Purbauli Panchayat Bhawan to former mukhiya Amar Kant Choudhary house in Sarai Rason area		
Scheme / Programme: MAINTENANCE old MR		
Package No:	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance - Beyond Maint.		
Work is a case of: New Connectivity/ Up gradation/ Maintenance -		
Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	Road sanctioned under New MP 2018 & awarded to Sarda Infracon. Work is in progress by New Contractor.
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	


Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	—
Unsatisfactory(U)	—

  
12/12/2020  
(Signature)

NAME:

DESIGNATION:

  
DR