


# FIELD INSPECTION REPORT

Date of Inspection: 12-12-2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 1.900 km.
Name of Road : NH 78 Panghalwafo Pupauli Village under Samastipur Area		
Scheme / Programme: MAINTENANCE		Old MR.
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance - Beyond Maint.		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance Road sanctioned under New MR 2018

Sl. No	Parameters to be Checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction Condition	N.A.
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Road sanctioned under New MR-2018. and awarded to Purnesh Const Pvt Ltd. Work under progress by New agency.
f)	Constraction Joint provided or not(CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridge	
3	<b>Road Furniture</b>	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	S
Unsatisfactory(U)	—

  
 (Signature)

NAME: Anil Prasad  
DESIGNATION: JE.