

# FIELD INSPECTION REPORT

Date of Inspection: 12.12.2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 4.320km	
Name of Road : NH28 Patrol pump (JK Enter Prices) to Barbalta.			
Scheme / Programme: MAINTENANCE		old M/R	
Package No:		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance Beyond Maint.			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked		Remarks
1	<b>Pavement</b>		
a)	Road Junction Condition	Road sanctioned under	
b)	Condition of Surfacing	PN 6Y. II awarded to	
c)	Riding Quality	Jagat Kishore Roy.	
d)	Road Camber	Work is in progress by	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	New Compaction	
f)	Constraction Joint provided or not(CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridge		
3	<b>Road Furniture</b>		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4	<b>Compliance History</b>		
a)	Status of ATR's & any others		


Overall Rating :

Satisfactory(S)	5
Satisfactory but requires Improvement(SRI)	—
Unsatisfactory(U)	—

  
 (Signature)

NAME:

DESIGNATION :

  
 05