


FIELD INSPECTION REPORT

Date of Inspection: 12.12.2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 5.220 Km	
Name of Road : Rampur Jole, Birnama Pahi Jole, Sa angara ghat Dalsinghsarai		
Scheme / Programme: MAINTENANCE - Old M/R		
Package No:	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance - under maintenance		
Work is a case of: New Connectivity/ Up gradation/ Maintenance - maintenance		
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes
f)	Constraction Joint provided or not(CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridge	—
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's & any others	No


Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	—
Unsatisfactory(U)	—


12/12/2020
(Signature)

NAME:

DESIGNATION :


SR