


FIELD INSPECTION REPORT

Date of Inspection: 12.12.2020		District: Samastipur
Division: RWD Dalsinghsarai		Length(km): 0.650km
Name of Road : Repair of Road from NH 28 Yogishtan to Salempur		
Scheme / Programme: MAINTENANCE old M/R		
Package No:		Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance - <u>Maintenance</u>		
Work is a case of:		New Connectivity/ Up gradation/ Maintenance <u>Maintenance</u>
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes
f)	Constraction Joint provided or not(CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	ND
2	Cross Drainage	NA
a)	Condition of head walls in Hume pipe culverts including its painting	- S -
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	- S -
c)	Condition of railings/slab/approach for Bridge	- S -
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's & any others	- No -

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement(SRI)	-
Unsatisfactory(U)	-


 (Signature)

NAME:

DESIGNATION :

Anil Prasad
 QS